

# Pressure gauges for pressure loss measurement

## Accessory equipment



Plus  
service

HVAC

Industry

### 1,000

#### Pressure gauge description

The acrylic U-tube is located in a steel case. The pressure gauge range is 0 – 1,000 Pa. The pressure gauge is supplied without accessories.

#### Measurement range

Optional (tube inclination setting):  
0 – 1,000 Pa

### 2,500

#### Pressure gauge description

The acrylic U-tube is located on a plastic scale. The pressure gauge is supplied with accessories.

#### Measurement range

Optional (tube inclination setting):  
0 – 2,500 Pa

#### Accessory equipment

Contrast liquid (blue), bushes, hoses and fastening screws.

### 5 000 – Magnehelic

#### Pressure gauge description

The scale with a range of 0 – 5,000 Pa is located in a metal case. The pressure gauge is supplied with accessories.

#### Measurement range

0 – 5,000 Pa

#### Accessory equipment

Bushes, hoses, and erection bolts.

**We supply the complete line of  
Magnehelic pressure gauges.**