


Pressure gauges for pressure loss measurement

Accessory equipment



7030 with an inclined tube

Pressure gauge description

The inclined tube (made of acrylic) with the possible setting of 2 ranges, i.e. 0 – 250 Pa and 0 – 500 Pa, is located in a plastic case. The vessel with contrast liquid is located in the back part of the case. The pressure gauge is supplied with accessories.

Measurement range

Optional (tube inclination setting):
0 – 250 Pa and 0 – 500 Pa.

7030-EK with inclined tube and electronic control (optional)

Pressure gauge description

The inclined tube (made of acrylic) with the possible setting of 2 ranges, i.e. 0 – 250 Pa and 0 – 500 Pa, is located in a plastic case. The vessel with contrast liquid is located in the back part of the case. The pressure gauge is supplied with adjustable electrical contacts for the connection to the measurement and control system.

Measurement range

Optional (tube inclination setting):
0 – 250 Pa and 0 – 500 Pa

Accessory equipment

Contrast liquid (blue), bushes, hoses and fastening screws.